THE LEAD REPAIR WORK ORDER.

A CRAFT SUPPORT WORK ORDER.

2. PAINT CREW 33 (B. LITTLE, x6866) HAS

D. CLEAN UP AFTER YOURSELF PLEASE.

PAINTING HAS BEEN COMPLETED.

E. NOTE ANY WORK PERFORMED BEYOND THE BASIC WORK OUTLINED ON IN THIS WORK ORDER.

C. DISMANTLE SCAFFOLD AND RETURN ALL

AREAS AFTER INSTALLATION, INSPECTION AND

MATERIALS TO THEIR DESIGNATED STORAGE

\*\* IMPORTANT NOTICE \*\*

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



7\_032349

CREW: 97 WORK ORDER TYPE: MODIFICATIONS

03-96033-40

ISSUE DATE 01/06/11

Page 2 Of 2

Step Job Scope Cont'd

MN DY Safety and Additional Information Cont'd

Notes Cont'd:

\*\* ADDITIONAL INSTRUCTION BY SUPERVISOR \*\*